



University of Agriculture in Krakow,
Faculty of Environmental Engineering
and Land Surveying



Department of Hydraulic
Engineering and Geotechnics

Habitat structure changes of the Wisłoka river as a result of channel restoration

Leszek Książek, Agnieszka Woś, Maciej Wyrębek, Andrzej Strużyński



XXXVIII

International School of Hydraulics

21 - 24 May 2019 • Łąck • Poland

Introducing the Water Frame Directive means improving river bed continuity, treating them as a ecological corridor.

Principles of surface water classification (according to the WFD)

**biological
parameters**

**physico-chemical
conditions**

**hydromorphological
conditions**

**State: very good, good,
moderate, weak, bad**

TASKS:

- improve structure of fish habitat in the section of the Wisłoka River (30 km),
- the modernization of 9 hydraulic structures located on the Wisłoka, Jasiołka and Ropa,
- fish stocking.

Hydromorphological quality classes

CHANNEL

1. Channel **geometry**, planform, longitudinal section, cross-section
2. Substrates – artificial, natural **substrate** type
3. Channel and bank **vegetation** and organic debris, structural form of macrophytes present, leafy and woody debris
4. Erosion/Deposition character, features in channel and at base of bank, point **bars**, eroding cliffs
5. **Flow**, flow patterns, flow Features, discharge regime, possibility of water **exchange** between the river bed and alluvial (river and hyporetic waters)
6. Longitudinal **continuity** as affected by artificial structures, artificial barriers affecting continuity of flow, sediment transport and migration for biota

RIVER BANKS/ RIPARIAN ZONE

7. **Bank structure** and modification, bank materials, types of bank protection
8. **Vegetation type/structure on banks** and adjacent land, structure of vegetation, types of land-use and type of development


FLOODPLAIN

9. Adjacent **land-use** and associated features, type of land-use, extent and type of development, type of open water/wetland features
10. Degree of **lateral connectivity of river and floodplain** and lateral movement of river channel, degree of constraint to potential mobility of river channel and water flow across floodplain

Hydromorphological quality (modification) classes:

- 1,0 ÷ 1,79 – Near natural,
- 1,8 ÷ 2,59 – Slightly altered,
- 2,6 ÷ 3,39 – Moderately altered,
- 3,4 ÷ 4,19 – Extensively altered,
- 4,2 ÷ 5,00 – severely altered.


Mezohabitats



Habitats – the living space of the water organisi, the zone on the river bed characterise by relatively constant flow parameters
Mezo – scale/dimension



The Vistula River



Hydraulic structure relevant to fish migration in the area of Low and Upper Vistula

Reconstruction of fish ladder – Włocławek Reservoir 2014



Reophile fish - fish that need to grow in fast moving, well-oxygenated water and gravel surfaces:



Trout, Pstrąg potokowy



Aspius aspius, Boleń

Diadromous fish - travels from the Baltic Sea (salt water) into rivers of spring sections (fresh water) to spawn:



Bull-trout, Troć




Salmon, Łosoś




- Ryby idą - trocie, certy, leszcze - mówi prof. Piotr Dębowski z Instytutu Rybactwa Śródlądowego w Olsztynie kierujący grupą ichtiologów, która przyjechała na tamę - Teraz przeszło około 200 troci. Mamy też silny ciąg certy. Wczoraj zanotowaliśmy sto kilkadziesiąt tych ryb na przepławce.

Channel incision of main rivers of the polish Carpatians during the 20th century and in second half [m]



The Raba, Skawa, Dunajec Wisłoka Rivers riverbed elevation lowering from 2 to 4 meters, the erosion concerns a tributaries as well

Changes of the river morphology




- placing boulders,
- controlled lateral erosion of banks
- deposition of bedload in the river channel

- ▶ **Concept**
- ▶ **Project**
- ▶ **Realization**
- ▶ **Monitoring**


Diversification of water flow conditions

Lateral erosion

Boulder clusters



Deposition of bed material




Dębica, below weir, section 07
 $Q_{\max} = 621 \text{ m}^3\text{s}^{-1}$ (16 May 2014)
 $Q_{\max} = 623 \text{ m}^3\text{s}^{-1}$ (13 Jul 2014)
Discharge $Q_{10\%}$, water depth $\sim h_{1\%}$



Spatial velocity distribution

Cross-sections



01-03, km 73+090
right after the boulder cluster –
openwork arrangement
 $Q=7.8 \text{ m}^3\text{s}^{-1}$;


02-09, km 71+309
downstream the deflector
 $Q=8.9 \text{ m}^3\text{s}^{-1}$,

09-03, km 54+482
downstream boulder cluster groups;
 $Q=11.9 \text{ m}^3\text{s}^{-1}$,

10-01, km 48+250
through openwork deflector
 $Q=13.6 \text{ m}^3\text{s}^{-1}$,

10-11, km 48+072
after the deflector outside the impact
zone; $Q=13.6 \text{ m}^3\text{s}^{-1}$.

Conversion of a homogeneous flow (riverbed) into a rich mosaic of habitats




Before (Q_{dec}):
riffie – 0.2%,
fast run – 7.4%,
run – 55.6%, shallow
water – 25.0%,
backwater – 11.9%,
pool – 0%.


After (Q_{pom}):
riffie – 0.8%,
fast run – 18.1%,
run – 33.2%,
pool – 23.5%, shallow
water – 13.9%,
backwater – 10.5%.

Low energy habitats
(shallow water and
backwater) from 36.9%
to 24.4% - decrease,
fast flow from 9.6% to
18.9% - increase
medium energy (pool) -
increase


River hydromorphological quality before and after restoration



The average; main channel with flood terraces: 2011 (before) – 3.25, 2014 (after) – 3.00.



River hydromorphological quality before and after restoration



The average; main channel without flood terraces: 2011 (before) – 3.02, 2014 (after) – 2.60.

Restoration did not include changes of bank protection and the river valley.

Conclusions:

- after restoration, all types are represented in the habitat structure. There is a noticeable decrease in the contribution of low energy habitats, the appearance of areas with medium energy and increase in areas with high energy habitats.
- channel restoration activities improved the morphological quality of the channel but did not cause a significant change of the all river valley - in seven locations increased their channel grade by one class.

The cumulative effect:


- **creating an ecological corridor of the river Wisłoka,**
- **reducing the fragmentation of the catchment area,**
- **restore the integrity of the NATURA 2000 "Wisłoka Tributaries".**

Thank you

rmksiaze@cyf-kr.edu.pl

lksiazek@urk.edu.pl

Dębica



Fishway project
Dębica, Wisłoka River km 56+180

